

GM Instrument Clusters 03 (06 USD)

Location **Ohio** https://www.genclassifieds.com/x-316765-z




If you own a GM product 2003-2006 and have 1 or more instrument gauges operating erratically, this could be a common problem with the OEM stepper motors. They have replaced these with an updated part number. I can resolve this issue for \$40 + \$5.00 per stepper motor. It is recommended to replace all stepper motors. You can bring/ship the cluster with prepaid return shipping included, or I can remove the cluster for an additional fee. Shipped back to you 24 hours after receiving.

Hours of Operation M-W,F 10a-5p Sat 10a-3p

1600 Cleveland Ave SW, 44707. Across from Sparkys (Hooch's) Bar and H&H Auto Parts) Like us on Facebook - Search Allens Auto and Used Tires.

Buick LeSabre 03-06 Rainier 04-06 Rendezvous 03-06

Cadillac Escalade 03-06



Trailblazer 03-06 Venture 03-05

GMC

Denali 03-06

Envoy 03-06

Sierra 03-06

Topkick 03-06

Yukon 03-06

Hummer H2 03-06

Isuzu

Ascender 03-06

Oldsmobile

Alero 03-04

Bravada 03-04

Silhouette 03-04

Pontiac

Aztek 03-05

Bonneville 03-05

Grand Am 03-05

Grand Prix 03-05

Montana 04-05

Sunfire 03-05

Location: