

# Headphone 3.5mm plug service replacement needed (Bangor)



Location **Maine**  
<https://www.genclassifieds.com/x-397780-z>



I'm seeking someone to supply and replace a 3.5mm plug on my studio monitor headphones. The old plug was tossed, but the spring and cap remain. Part of the outer wire has been stripped exposing a red (right audio), green (left audio) and black (ground) inner wire. Experience and excellent soldering skills are a must.

You can pick the headphones up or I can mail them. I'll gladly pay for transportation or postage both ways, whichever you prefer. In addition, I will compensate you for the part and your labor rate (negotiable).

Price isn't really an obstacle; I just really need someone who knows what they're doing and preferably has done this many times before.



Headphone 3.5mm plug  
 service replacement needed  
 (Bangor)

<https://www.genclassifieds.com/x-397780-z>



Headphone 3.5mm plug  
 service replacement needed  
 (Bangor)

<https://www.genclassifieds.com/x-397780-z>



Headphone 3.5mm plug  
 service replacement needed  
 (Bangor)

<https://www.genclassifieds.com/x-397780-z>



Headphone 3.5mm plug  
 service replacement needed  
 (Bangor)

<https://www.genclassifieds.com/x-397780-z>



Headphone 3.5mm plug  
 service replacement needed  
 (Bangor)

<https://www.genclassifieds.com/x-397780-z>



Headphone 3.5mm plug  
 service replacement needed  
 (Bangor)

<https://www.genclassifieds.com/x-397780-z>



Headphone 3.5mm plug  
 service replacement needed  
 (Bangor)

<https://www.genclassifieds.com/x-397780-z>



Headphone 3.5mm plug  
 service replacement needed  
 (Bangor)

<https://www.genclassifieds.com/x-397780-z>



Headphone 3.5mm plug  
 service replacement needed  
 (Bangor)

<https://www.genclassifieds.com/x-397780-z>



Headphone 3.5mm plug  
 service replacement needed  
 (Bangor)

<https://www.genclassifieds.com/x-397780-z>