

## Need companion code turned off in 2006 Sprinter (campbell)

Location **California** https://www.genclassifieds.com/x-633341-z



My Sprinter threw code P0715 on my OBD II scanner. That equates to the 2227 code on a DRBIII scanner, meaning that the voltage from the two speed sensors in the tranni is faulty. With the help of the major forums online, I believe to have fixed the problem by dropping the valve body and cleaning the sensors. The code throws a companion code to the tranni that my OBDII tool cannot turn off. If you have a DRBIII tool that can do this I would love to hear what you would charge me for this.

Need companion code turned off in 2006 Sprinter (campbell)
https://www.genclassifieds.com/x-6 33341-z
Need companion code turned off in 2006 Sprinter (campbell)
https://www.genclassifieds.com/x-6 33341-z
Need companion code turned off in 2006 Sprinter (campbell)
https://www.genclassifieds.com/x-6 33341-z
Need companion code turned off in 2006 Sprinter (campbell)
https://www.genclassifieds.com/x-6 33341-z
Need companion code turned off in 2006 Sprinter (campbell)
https://www.genclassifieds.com/x-6 33341-z
Need companion code turned off in 2006 Sprinter (campbell)
https://www.genclassifieds.com/x-6 33341-z
Need companion code turned off in 2006 Sprinter (campbell)
https://www.genclassifieds.com/x-6 33341-z
Need companion code turned off in 2006 Sprinter (campbell)
https://www.genclassifieds.com/x-6 33341-z
Need companion code turned off in 2006 Sprinter (campbell)
https://www.genclassifieds.com/x-6 33341-z
Need companion code turned off in 2006 Sprinter (campbell)
https://www.genclassifieds.com/x-6 33341-z