
VW Bug Heater Channel Door Jamb Rocker Repair Metal Sections Beetle (25 USD)





Good solid LH drivers side door jamb section, of the heater channel / rocker. Came off a 1970 Volkswagen sedan bug. Some pitting around the heater vent opening, some west coast surface rust here and there, no holes and rot through anywhere. Passenger side RH door jamb section. Some west coast surface rust here and there, some small rust holes on the bottom side. I assume these fit 68 up standard and Super Beetle. These are both form a 70 standard beetle sedan.

\$25. for both.

I reply by EMAIL, NO text.















W Bug Heater Char imb Rocker Repa actions
Heater ocker I
ter -



























https://www.genclassifi 94791-z	

eds.com/x-6

Sections	Jamb Rocker	VW Bug Heater
Œ	Repair 1	Channel

