

Experienced RooferSmall RepairSteepampHigh Roof (East Windsor)

hide this

Location Connecticut https://www.genclassifieds.com/x-752465-z



QR Code Link to This Post Need to coat over a crack in the flashing @ the base of the chimney. Want to use brushable "Through the Roof" product, which I have; stuff is about as thick as syrup. The Karnak there has failed. Crack is a couple of feet long.

Not looking for a guaranteejust do it for me my way, and I'll take my chances.

Roof is 30 feet high, and 12/12 pitch. It can be accessed from an adjacent shallow sloped roof, or from the front using a long extension ladder ,etc. your call here.

Am serious, not a dreamer .Will pay cash for you and for a helper. Use your equipment. Can send pictures. If you are also serious, I'll pay for your gas/etc to get over and take a look (so you do not get stiffed with a " free estimate " but no job.) Dad always taught me that cash talks, everything else walks .

Email works best for now.....hearing over a phone is not good. Name is Bill.

Lets talk, before the snow and ice gets here.

e mail is best for now, as my hearing is not good.

52465-z	https://www.ge	this posting	(East Winds	RepairSteep	Experience	










(East Windsor)	RepairSteepampHigh	Experienced	
	l igh	Roc	
hide	Roof	RooferSmal	



this posting unh https://www.genclassifieds.com 52465-z	Experienced Ro RepairSteepampHigh (East Windsor)
ssifieds	Roo High
unh s.com	RooferSr igh Roo h



52465-2	https://www.genclassifieds.cor	this posting	(East Windsor)	RepairSteepampHigh	Experienced	
	sifieds			igh	RooferS	
	s.cor	un		Ro	ferS	





				_	
https://www.genclassifieds.c	this posting	(East Windsor)	RepairSteepampHigh I	Experienced Roofe	

52465-z
-

Experienc RepairSteepa (East Windso this posting https://www.ge 52465-z	1

7 7 6				
52465-z	https://www.genclassi	this posting	(East Windsor)	RepairSteepampHi

RooferSmall



this posting https://www.genclassifi 52465-z	RepairSteepampHig (East Windsor)