











67 (72 USD)



Location **Washington**
<https://www.genclassifieds.com/x-695642-z>

A complete standard heater control with all 3 cables, good for repair parts or fix it and use it as is. All 3 sliding arms intact and work good and 3 cables move like they should. The rear metal housing attaches to the face plate by pop rivets, the rivets have come apart on the back side. see pic with red circles. Should be an easy fix with a rivet gun, epoxy or some small screws to reattach the metal housing.

Will delete when.

 https://www.genclassifieds.com/x-695642-z 67	 https://www.genclassifieds.com/x-695642-z 67	 https://www.genclassifieds.com/x-695642-z 67	 https://www.genclassifieds.com/x-695642-z 67	 https://www.genclassifieds.com/x-695642-z 67	 https://www.genclassifieds.com/x-695642-z 67	 https://www.genclassifieds.com/x-695642-z 67	 https://www.genclassifieds.com/x-695642-z 67	 https://www.genclassifieds.com/x-695642-z 67	 https://www.genclassifieds.com/x-695642-z 67
---	--	--	--	---	--	--	--	--	--